

Replacement Pinions and Gears For GE* Locomotives

GE PINIONS	
Teeth	Part Number
14	4767063
15	343B904P1
15	41C633598P1
	4767988P1
15	4767994
15	6722460P1
15	6722476P1
15	41635966P1
	8824147P1
16	4767979GRM
16	K6722442P2
16	8837767P1
16	41D735826P1
16	41D735825P1*
16	84D730389P1*
16	84D730335P1*
17	41C632382P2
17	41C633677P1
17	41C635963P1
	8822316P1
17	41C637180P1
	8828155P1M
	41A230112P1
17	4767997
17	8837776
18	8828170P1
18	84C730376P1
18	41C635677P2
18	41C637903P1
18	41C635796P1
18	41C637399P1
	41C632481P1
19	41C632785P2
	8828153P1
19	41C633596P1
19	41C635176P1
20	84C614909P1
	41A230113P1
20	41C636447P6
	41C635597P2
20	84C620834P2
21	41C637595P1
	8828169P1
21	41C632947P1
21	41C633558P1
22	41C637249P1
	41C632501P1
23	41C632660P1
24	41C632339P1

GE BULL GEARS	
Teeth	Part Number
55	41C633592P1
	8837795P1
65	41C635820P1
	6733009P1
71	41C633537P1
72	41C635969P1
72	41C635969P2
72	8837743P1
72	41C633601P1
74	41C637442P2
74	41C632494P1
76	2792468
76	41C633597P1
81	41C632502P1
82	41C632948P1
83	41C635598P1
83	41C636806P3
83	41C637055P5
83	41A330128G3
83	41C637055P4
87	41D735826P2
90	41C632381P1
90	41C632381P2
90	41C637598P1
	8837760P1
90	41C637962P1
90	84A203132G1
91	41B530121P1
91	41B530121P2
92	41C632784P1
92	41C632784P2
93	41C636682P1
	8837756P1
93	41C636682P1A
93	41C636682P2
93	41C636682P3
93	41C636682P4
94	41C637211P1
	8837727P1
94	41C637902P1

GE ARMATURE SHAFTS	
Motor	Part Number
752AG9	41C635780G2
752AG, AH	41C637691P1
761	41C637265G1
	8843544G1
842	6738485P1
5GEB13E A4	41D735826P1
5GEB13E	41D735825P1**
	84D730389P1*
	84D730335P1*
	**IPS (short body)

* Part availability continues to expand.

Call if your requirements if not shown on this list.

* GE is a trade designator of General Electric. Penn Machine Company is not an authorized GE distributor, nor is otherwise associated or affiliated with GE. However, Penn Machine Company does represent that its replacement parts, components, subsystems, and services are compatible with and usable on GE locomotives.